

**Please call GE now even if you have previously called  
and did not get through.**

# **GE APPLIANCES**

## **Supplemental Dishwasher Recall**

Over a year ago, GE, in cooperation with the U.S. Consumer Product Safety Commission, recalled certain GE and Hotpoint Dishwashers manufactured between April 1983 and January 1989. The slide-type switch used to select either energy saver drying or heated drying can melt or ignite, presenting a fire hazard.

Through the supplement to the program, GE is offering free rewiring, or a cash rebate certificate of \$25-\$125 toward the purchase of any new dishwasher which was part of the original recall. Although the rewire will not extend the life of the dishwasher, both options eliminate the hazard. The choice is yours.

If you own one of these units and have not taken action, please do so immediately.

The dates the units were manufactured are between April 1983 and January 1989. The models' serial numbers are:

---

GSD500D	Serial numbers containing, A, M, R, S, T, V, Z as the second character (for example, BM12345).
GSD500G	
GSD540	
HDA467	Note: The second character of the dishwasher must contain one of the listed letters. Here is an example: FM234567
HDA477	
HDA487	

**If you own one of these dishwashers  
immediately discontinue use and contact  
GE at**

**1-800-599-2929**